LEAD SERVICE LINE INVENTORY SUMMARY

| Service Line Classification | Service Lines Owned by Saraland Water and Sewer Service | Service Lines Owned by Property Owner |
|-----------------------------|--|--|
| Lead | 0 (0%) | 0 (0%) |
| Lead-Lined Galvanized | 0 (0%) | 0 (0%) |
| Galvanized | 0 (0%) | 20 (< 0.5%) |
| Unknown – Likely Lead | 0 (0%) | 0 (0%) |
| *Unknown – Unlikely Lead | 1818 (+/- 44%) | 1818 (+/- 44%) |
| Unknown – Material Unknown | 0 (0%) | 0 (0%) |
| Non-Lead – Copper | 2296 (+/- 56%) | 1267 (+/- 31%) |
| Non-Lead – Plastic | 1 (< 0.1%) | 1010 (+/- 25%) |
| Non-Lead – Other | 0 (0%) | 0 (0%) |

* Service Line Classification "Unknown – Unlikely Lead" – Service lines in this classification are unlikely lead because they were installed after the Lead Ban, which took effect in January 1989.